

## Yealink SIP CP860 IP Phone Release Notes

### Table of Contents

Yealink SIP CP860 IP Phone Release Notes .....	1
Yealink SIP CP860 IP Phone Release Notes of Version 37.72.0.10 .....	2
1. Introduction .....	2
2. New Features .....	2
3. Optimization.....	2
4. Bug Fixes.....	2
Yealink SIP CP860 IP Phone Release Notes of Version 37.72.0.5 .....	3
1. Introduction .....	3
2. New Features .....	3
3. Optimization.....	3
4. Bug Fixes.....	3

## Yealink SIP CP860 IP Phone Release Notes of Version 72

### 1. Introduction

- Firmware Version:  
CP860: 37.72.0.5 upgrades to 37.72.0.10
- Applicable Models: CP860
- Release Date: Jun 26<sup>th</sup>, 2015.

### 2. New Features

### 3. Optimization

- Optimized the voice quality on the CP860.
- Fixed the issue that the volume was a little low of the phone speaker, the maximum volume was now be modified.

### 4. Bug Fixes

- Fixed the issue that the recording files was displayed OKB sometimes when it was played on the computer.
- Fixed the issue that the music was stuck when it was played through the mobile phone.

## Yealink SIP CP860 IP Phone Release Notes of Version 72

### 1. Introduction

- Firmware Version:  
VC400: 37.72.0.3 upgrades to 37.72.0.5
- Applicable Models: CP860
- Release Date: Mar 18<sup>th</sup>, 2015.

### 2. New Features

### 3. Optimization

- Optimized the sound quality of the phone, especially the echo cancellation.
- Optimized the PC-Mobile Mode feature. Only when the audio line connected to the mobile phone and computer, the phone will enter the PC-Mobile Mode.

### 4. Bug Fixes

None